EAST Search History

EAST Search History (Prior Art)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	592	motor and bracket and dryer and shaft and fan	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	OR	OFF	2009/09/28 08:01
L2	6	motor and bracket and dryer and shaft and fan and chamfer	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	OR	OFF	2009/09/28 08:02
L3	64	("1773148" | "2025029" | "2128827" | "2139545" | "2146293" | "2233555" | "2249755" | "2288444" | "2297459" | "2299269" | "2351202" | "2353256" | "2482418" | "2631108" | "2712161" | "2731668" | "2814069" | "2814834" | "2867847" | "2889291" | "2923598" | "2973333" | "3166791" | "3270710" | "3278991" | "3617588" | "3694117" | "4377603" | "4495229" | "4684490" | "4817593" | "4895101" | "4917850" | "4988277" | "4993935" | "5112555" | "5116551" | "5391343" | "5667822").PN. OR ("6273702").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/09/28 08:02

L4	67	("1169733" | "1180358" | "1380862" | "2025029" | "2128827" | "2139545" | "2146293" | "2233555" | "2241176" | "2249755" | "2251108" | "2288444" | "2297459" | "2299269" | "2351202" | "2353256" | "2482418" | "2712161" | "2731668" | "2814069" | "2814834" | "2889291" | "2923598" | "2973333" | "3166791" | "3270710" | "3278991" | "3694117" | "4298955" | "4377603" | "4495229" | "4684490" | "4817593" | "4895101" | "4917850" | "4988277" | "4993935" | "5112555" | "5391343").PN. OR ("6231326").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/09/28 08:02
L5	59	("2025029" | "2128827" | "2139545" | "2146293" | "2233555" | "2249755" | "2288444" | "2297459" | "2299269" | "2351202" | "2353256" | "2482418" | "2712161" | "2731668" | "2814069" | "2814834" | "2889291" | "2923598" | "2973333" | "3166791" | "3270710" | "3278991" | "3694117" | "4377603" | "4495229" | "4684490" | "4817593" | "4855169" | "4895101" | "4917850" | "4988277" | "4993935" | "5112555" | "5391343").PN. OR ("6217815").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/09/28 08:02
L6	35	("1483664" | "1814713" | "2116916" | "2146293" | "2155977" | "2249755" | "2299269" | "2351202" | "2353256" | "2482418" | "2712161" | "2814069" | "2814834" | "3166791" | "3278991" | "4377603" | "4684490" | "4988277" | "4993935" | "5112555").PN. OR ("6190155").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/09/28 08:02

L7	34	("1483664" | "1814713" | "2116916" | "2146293" | "2249755" | "2299269" | "2351202" | "2353256" | "2482418" | "2712161" | "2814069" | "2814834" | "3166791" | "3278991" | "4377603" | "4684490" | "4988277" | "4993935" | "5112555" | "5527173"). PN. OR ("6106748"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/09/28 08:03
L8	1	("2109028").URPN.	USPAT	OR	OFF	2009/09/28 08:03
L9	7	(motor and bracket and dryer and shaft and fan). clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	OR	OFF	2009/09/28 08:04
L10	0	("2006/0048406").URPN.	USPAT	OR	OFF	2009/09/28 08:12
L11	0	("2004/0221477").URPN.	USPAT	OR	OFF	2009/09/28 08:12
L12	9	("2181436" | "3102961" | "3914955" | "4339743" | "6224335" | "6270559" | "6746215").PN. OR ("7367201").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/09/28 08:12
L13	2	("5555647" | "6874248"). PN. OR ("7350319"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/09/28 08:12
L14	15	("4765066" | "5146693" | "5187879" | "5463821"). PN. OR ("5983520"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/09/28 08:12
L15	36	("1564896" | "1821525" | "2432067" | "2713627" | "3211890" | "3284611" | "3905379" | "3939850" | "3943329" | "3981314" | "4135080" | "4232454" | "4593179" | "4596921" | "4678410" | "5054211" | "5161317" | "5317815" | "5341578" | "5392528" | "5471763").PN. OR ("5841943").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/09/28 08:12

L16	37	("1130383" | "2776640" | "2908249" | "3391670" | "3853092").PN. OR ("4092952").URPN.	US-PGPUB; USPAT; USOCR	OR		OFF	2009/09/28 08:13
L17	107	8 9 12 13 14 15 16	US-PGPUB; USPAT; USOCR	OR		OFF	2009/09/28 08:14

EAST Search History (Interference)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L18	0	(motor and bracket and dryer and shaft and fan and chamfer).clm.	USPAT; UPAD	OR	OFF	2009/09/28 08:15
L19	0	(motor bracket dryer shaft fan chamfer).clm.	USPAT; UPAD	AND	OFF	2009/09/28 08:15
L20	5	(motor bracket dryer shaft fan).clm.	USPAT; UPAD	AND	OFF	2009/09/28 08:15

9/28/2009 8:32:56 AM
C:\ Documents and Settings\ sgravini\ My Documents\ EAST\ Workspaces\ default.wsp